

Quiz 2 – Properties-Microstructure-Processing Callister Chapters, 7,3,4

You need to know/be able to

- Name the two types of solid solutions (interstitial and substitutional) and explain how they differ.
- Describe the difference between amorphous and crystalline and state how that structure affects properties.
- Name the three most common types of unit cells for metals and explain how the unit cell affects properties
- *State the relationship of dislocation motion and planar slip on the behavior of metals, and explain how it affects strength and ductility.*
- For the following processes, determine (from graphs and/or calculations) the strength/ductility and describe the governing microstructural mechanism
 - Solid Solution Strengthening
 - Grain Size Refinement
 - Cold Work and Annealing
- For Cold Work and Annealing
 - Calculate %cold work from change in cross-sectional geometry
 - Describe the microstructural and property changes during *Recovery, Recrystallization and Grain Growth*, and the relationship between microstructure and properties
 - Use tables and graphs (such as fig. 7.19) to design a process that will produce a set of desired properties

Vocabulary

Chapter 7

Cold working

Dislocation Density

Grain Growth

Lattice Strain

Recovery

Recrystallization

Recrystallization Temperature

Slip

Slip System

Solid-solution strengthening

Strain hardening

Chap 3

Amorphous

Anisotropy

Body-centered-cubic

Crystal structure

Crystalline

Face Centered-cubic

Grain

Grain Boundary

Hexagonal close-packed

Isotropic

Noncrystalline

Polycrystalline

Unit cell

Chap 4

Alloy

edge dislocation

interstitial solid solution

microstructure

screw dislocation

solid solution

solute

solvent




substitutional solid solution

vacancy

Exam 2 Review



Metal Crystal Structures

Type	Name	Properties	Example
FCC	Face-Centered-cubic	Ductile at all temps	Aluminum, copper, Nickel
BCC	Body-centered-cubic	ductile-brittle transition with temp or strain rate	Iron (steel) tungsten
HCP	Hexagonal-close-packed	less ductile	Magnesium, zinc

<p>FCC</p> 	<p>This is a close packed structure (packing factor is 0.74, max possible). Has close packed planes and close packed directions in several orientations.</p>	<p>Excellent slip systems leads to excellent ductility</p>
<p>BCC</p> 	<p>Not a close packed structure (packing factor of 0.68). No close packed planes, several close packed directions.</p>	<p>Good slip systems lead to good ductility unless cold or rapidly loaded</p>
<p>HCP</p> 	<p>Close packed structure with close packed planes and directions. Unfortunately, the planes are only in one orientation.</p>	<p>One excellent slip system in a single orientation leads to less ductility. (Mag wheels vs Al wheels)</p>

(Figures from Materials Science and Engineering, An Introduction by Callister)

Dislocations

	<p>Edge Dislocation: An "extra" half plane of atoms; a line defect in a crystal</p>		<p>Screw Dislocation: A line defect similar to a tearing a phone book.</p>
---	---	--	--

(Figures from Materials Science and Engineering, An Introduction by Callister)

Importance: Dislocations make planar slip much easier. Since only one row of atoms moves at a time, many fewer atomic bonds must break for plastic deformation to occur

Grand Truth - Strengthening in metals

1. Yield strength is the onset of plastic flow
2. Plastic flow results from planar slip
3. Planar slip results from dislocation motion

Therefore

To increase Strength - Prevent/Impede Dislocation Motion

Ductility Corollary


1. Impeding dislocation motion makes slip harder
2. Lower slip means lower ductility

Therefore:


Increasing Strength generally Lowers Ductility

Strengthening Methods for Metals


Grain Size Reduction - Small grained metals are stronger than coarse grained metals

<p>Yield Strength</p>  <p>Effect of Grain Size Reduction</p>	<p><u>Mechanism:</u> Grain boundaries block dislocation motion. More grains (smaller grains) means more boundaries and more blocking of dislocations</p>	<p><u>Process:</u> Cold work to add internal energy, anneal to recrystallize and form new small grains. <u>Note:</u> Strength increases without loss of toughness</p>
--	--	---

Solid Solution Strengthening - Often alloying with a second element increases strength

<p>Strength</p>  <p>Solid Solution Strengthening</p>	<p><u>Mechanism:</u> Solute atoms are too big or too small and cause distortion ins the crystal lattice</p>	<p><u>Process:</u> Add other elements to the melt e.g. add Al and V to Ti to get Ti6Al4V.</p>
---	---	---


Strain Hardening (Cold Work) - Plastic deformation often increases strength

<p>Yield Strength</p>  <p>Effect of Plastic Deformation</p>	<p><u>Mechanism:</u> Number of dislocations increases by orders of magnitude, distorting lattice and impeding dislocations</p>	<p><u>Process:</u> Mechanically deform plastically. (e.g. cold roll, wire draw)</p>
--	--	---

Annealing - Reversing the effects of Strain Hardening

Stages


- **Recovery** - residual stresses are relieved
- **Recrystallization** - If previously cold worked, new equiaxed, strain-free grains nucleate from high energy regions.
- **Grain Growth** - Grains grow with higher temperature and longer time (diffusion -)



%Cold Work

The %Cold work is the %area reduction of the cross section

$$\%CW = \frac{A_0 - A_1}{A_0} (100\%)$$



In Cold rolling only thickness changes