

---

# Surface micromachining and Process flow part 1

---

- Identify the basic steps of a generic surface micromachining process
  - Identify the critical requirements needed to create a MEMS using surface micromachining
  - List common structural material/sacrificial material/etchant combinations used in surface micromachining
  - Compare and contrast the relative merits of wet micromachining versus dry micromachining
  - Explain the phenomenon of **stiction**, why it occurs, and methods for avoiding it
  - Describe the process of **lift-off**
  - Explain what is meant by **packaging** and describe the ways in which it present major challenges in MEMS
  - Calculate the **resolutions** of the above processes and explain what they depend on and why
- Define the terms
    - Structural layer/material**
    - Sacrificial layer/material,**
    - Release, and**
    - Die separation**
  - Develop a basic-level process flow for creating a simple MEMS device


## Surface micromachining example – Creating a cantilever

Deposit poly-Si (\_\_\_\_\_—  
the Jenga pieces that remain)

Deposit SiO<sub>2</sub> (\_\_\_\_\_—the  
Jenga pieces that are removed)

Etch part of  
the layer.

Remove sacrificial  
layer (\_\_\_\_\_)



Silicon wafer (Green  
Lego® plate)

# Reminder of the surface micromachining process

side view



top view



 silicon

 oxide

 metal

# Process flow for surface $\mu$ -machined cantilever




Mask 1 (negative resist)




Mask 1 (positive resist)





Top view (4)




Top view (5)



Top view (6)



# Process flow for surface $\mu$ -machined cantilever



# History and processes

- Surface micro-machining (SMM)
- Developed in the early 1980s at the University of California at Berkeley
- Originally for \_\_\_\_\_ mechanical structures
- Other processes include
  - Sandia National Lab's SUMMIT (Sandia's Ultra-planar Multi-level MEMS Technology) → five levels possible with four poly layers
  - MEMS CAP's polyMUMPs (Multi User MEMS Processes) → three layers of poly with a layer of metal





Photo of a PolyMUMPs surface-micromachined micro-mirror. The hinge design allows for out-of-plane motion of the mirror.

# Requirements and advantages

- Three to four different materials required in addition to the substrate
  - \_\_\_\_\_ material (etch rate  $R_j$ )
  - \_\_\_\_\_ mechanical material (etch rate  $R_m$ )
  - Sometimes \_\_\_\_\_ and/or \_\_\_\_\_ materials (etch rate  $R_j$ )
- Many SMM processes are compatible with \_\_\_\_\_ (complementary metal oxide silicon) technology used in microelectronics fabrication.
- Can more easily \_\_\_\_\_ with their control \_\_\_\_\_ on the same chip
- Many SMM processes have developed their own




Best results are obtained when structural materials are deposited with good \_\_\_\_\_.

Chemical vapor deposition (CVD)  
or  
Physical vapor deposition (PVD)

If PVD

Sputtering  
or  
Evaporation



# Common material/etchant combinations for surface $\mu$ -machining

Structural material	Sacrificial Material	Etchant
<b>Si/Polysilicon</b>		
<b>Al</b>		
<b>Polyimide</b>		
<b>Si<sub>3</sub>N<sub>4</sub></b>		


# Problems and issues

## Wet etching

- 40 years of experience and data in the semiconductor industry
- Ability to remove \_\_\_\_\_
- Very high \_\_\_\_\_
- Usually \_\_\_\_\_ → always involve \_\_\_\_\_

## Dry etching

- Better \_\_\_\_\_ than wet etching
- More \_\_\_\_\_ (High \_\_\_\_\_)
- \_\_\_\_\_
- No \_\_\_\_\_



# Stiction

$$\begin{aligned} \text{Stiction} &= \underline{\hspace{2cm}} + \underline{\hspace{2cm}} \\ \text{Stiction} &= \underline{\hspace{2cm}} + \underline{\hspace{2cm}} \end{aligned}$$

An example of a \_\_\_\_\_

An example of an \_\_\_\_\_


$$\frac{\text{surface tension}}{\text{restorative force}} = \frac{\sigma}{F} \sim \underline{\hspace{2cm}} \sim \underline{\hspace{2cm}}$$

Ways to reduce stiction

- 
- 
- 




# Problems and issues



Polysilicon hotarm actuator created using surface  $\mu$ -machining

Explain (with words, drawings, or both) how standoff bumps might be created.

Usually included as an “additive technique” by most authors



(+) or (-) resist?


1. Photoresist is spun on a wafer and exposed to create pattern  
Resist has either \_\_\_\_\_, or better, a \_\_\_\_\_ shape.
2. Material deposited through the photoresist mask using a \_\_\_\_\_, such as \_\_\_\_\_
  - \_\_\_\_\_ takes place,
  - Part of the photoresist sidewalls must be free of deposited material
3. Photoresist stripped leaving behind only material deposited through the opening. Unwanted material is \_\_\_\_\_.

Thickness of the \_\_\_\_\_ material must be \_\_\_\_\_ compared to the \_\_\_\_\_ thickness.


Most often used to deposit \_\_\_\_\_, especially those that are hard to etch using plasmas



# Die separation and packaging




- Must \_\_\_\_\_ the individual devices
- Often \_\_\_\_\_ or \_\_\_\_\_ the wafer
- Provide MEMS device with \_\_\_\_\_  
\_\_\_\_\_
- \_\_\_\_\_ MEMS from the \_\_\_\_\_
- Sometimes must \_\_\_\_\_  
to environment (e.g., pressure sensor, inkjet print heads)
- Packaging a difficult engineering problem
- \_\_\_\_\_ of producing many (most) devices




# More on packaging

\_\_\_\_\_ packaging



\_\_\_\_\_ packaging




packaging



## More on packaging

Schematic of a packaged MEMS pressure detector showing some of the requirements unique to MEMS



# Process integration (Process flow)


We have learned much about the many materials and techniques for used processing materials to create devices, including

- Nature of crystalline silicon
- Adding material
  - \_\_\_\_\_
  - \_\_\_\_\_
  - \_\_\_\_\_
    - \_\_\_\_\_
    - \_\_\_\_\_
- Photolithography
- Bulk Micromachining
- Surface Micromachining

How do we put these things together to create a device?

Specifically:


- \_\_\_\_\_?
- \_\_\_\_\_?
- \_\_\_\_\_?



**Process integration  
(Process flow)**




# Bulk $\mu$ -machined pressure sensor



- Thin Si diaphragm changes shape when pressure changes on one side relative to the other.
- Piezoresistors (implemented using  $p^+$  diffusion) sense the deformation.
- Aluminum wires send resistive electrical signal off the chip.
- $n^+$  diffusion is used as an etch stop for the backside etch.
- Oxide + Nitride provides wafer protection for backside etch and insulator between Al wires and wafer.

## Process flow, pass 1


The first pass for determining the process flow is to decide which steps we need.



What are the basic steps necessary to build the **diaphragm**?

## Process flow, pass 1


The first pass for determining the process flow is to decide which steps we need.



What are the basic steps necessary to build the **sensor**?

## Process flow, pass 1

The first pass for determining the process flow is to decide which steps we need.




What processing steps are required to produce entire device?

Each of these steps results in more steps in the detailed process flow. But to begin, let's determine the **order** in which the steps must be placed.

## Order of steps

What impacts our decisions on choosing an order?

1. **Geometry**
2. **Temperature**



3. **Mechanical stress**

Which processes are high T?

- \_\_\_\_\_
- \_\_\_\_\_
- \_\_\_\_\_

4. **Interaction of chemicals**

## Order of steps

Let's choose an order

1. \_\_\_\_\_



2. \_\_\_\_\_:

3. \_\_\_\_\_

4. \_\_\_\_\_

Do we do backside etch or metallization next?

Can we pattern nitride and oxide on both front and back at the same time?



## Order of steps



Let's choose an order

5. \_\_\_\_\_:

6. \_\_\_\_\_:

7. \_\_\_\_\_:

8. \_\_\_\_\_:



## Pass 2, Detailed process flow

A detailed process flow is the list of all steps necessary for the process people to implement the device. It should include each of the following:

1. All steps in the proper order, including when to clean the wafer
2. Any chemicals necessary
3. Thicknesses of materials
  - These choices come for modeling.
  - The “process people” can turn chemicals and thicknesses into times necessary for etches, depositions, etc.

### 4. Equipment necessary

It is the responsibility of the process flow person to think about which equipment is necessary for each step. Why? Because if you need a high temperature deposition to follow a metallization, you need a PECVD to do it or your metal will flow. The process flow person knows the entire process and makes design decisions.

### 5. MASKS for photolithography

# Detailed process flow

Let's revisit each of the basic steps that we came up with and see what is really involved. You will notice that many of the steps actually turn into several steps when coming up with the detailed process flow. For this exercise, we will **ignore dimensions and chemicals**. However, note that these are also important components of the design flow.

## 1. n-type doping

a. Mask?

b.

i.

ii.

## 2. Oxide

a. Mask?

b.

c.




# Detailed process flow

## 3. Dope resistors and wires

- a. Mask 1 – what does it look like? (Assume positive resist.)
- b. This step requires \_\_\_\_ total steps

Mask 1



## 4. Deposit nitride

- a. Mask?
- b. Depending on the process, you may need to process \_\_\_\_\_ of the wafer.
  - i. PVD
  - ii. CVD





## 5. Backside etch

a. Mask 2 – what does it look like? (Assume positive resist.)

b. Must align Mask 2 with Mask 1 so that  
\_\_\_\_\_ → \_\_\_\_\_  
\_\_\_\_\_

c. This step requires \_\_\_\_ steps



Mask 2



## 6. Contact Cuts/Diaphragm cut

- Mask 3 – what does it look like? (Assume positive resist.)
- Must align Mask 3 with \_\_\_\_\_ so that wires connect to resistors. → \_\_\_\_\_
- This step requires \_\_\_ total steps



Mask 3



## 7. Metallization

- Mask 4 – what does it look like? (Assume positive resist.)
- Must align Mask 4 with \_\_\_\_\_ so that metal \_\_\_\_\_  
\_\_\_\_\_. → *Alignment marks*
- This step requires \_\_\_\_ total steps

Mask 4



## Pass 3, Final process flow

These steps can be combined to create a **final process flow**.

One additional requirement in process flows is to include information about **when to clean the wafer**. Some general guidelines are:

- Always start with an \_\_\_\_\_ and an **HF dip** to get rid of every possible
- All future cleans are usually RCA cleans *without an HF dip*. HF may etch away your MEMS structures.
- *Always* \_\_\_\_\_ and \_\_\_\_\_ before high temperature processes.
- *Always* clean before \_\_\_\_\_.

## Final Process Flow for Bulk Micromachined Pressure Sensor

Starting material: 100mm (100) p-type silicon,  $1 \times 10^{15} \text{ cm}^{-3}$  boron with a 10 mm n-type epilayer,  $5 \times 10^{16} \text{ cm}^{-3}$  phosphorus

- 1. Clean:** Standard RCA clean with HF dip
- 2. Oxide:** Grow  $\text{SiO}_2$  on both sides of wafer
- 3. Photolithography:** Mask 1 (alignment)  
*Note: since the first patterned material is diffusion, which you cannot see, you must add alignment marks in the wafer or the first material you can see. If the first patterned material is something you can see, you do not need a separate alignment mark mask.*
- 4. Etch:** Etch alignment marks into  $\text{SiO}_2$ .
- 5. Strip:** Strip photoresist  
*Note: since the next step is not a material deposition or a high temp step, a clean is not necessary.*
- 6. Photolithography:** Mask 2 (piezoresistors)
- 7. Implant:** Ion implantation of boron to achieve  $1 \times 10^{19} \text{ cm}^{-3}$  at surface after drive-in
- 8. Strip:** Strip photoresist  
*Note: following step is a high temp step, so must clean wafer before.*
- 9. Clean:** RCA cleans, no HF dip
- 10. Drive-in:** Drive in diffusion to achieve 0.2  $\mu\text{m}$  junction depth  
*Note: following step is a material deposition, so must clean wafer before.*
- 11. Clean:** RCA cleans, no HF dip
- 12. Nitride:** Deposit 50 nm silicon nitride using LPCVD
- 13. Photolithography:** Mask 3 (backside photolithography for the diaphragm)
- 14. Etch:** Remove nitride and oxide from back of wafer
- 15. Backside etch:** Etch backside with KOH using electrochemical etch stop  
*Note: photoresist strip not necessary since returning to topside of wafer and strip will be done later for topside processing.*
- 16. Photolithography:** Mask 4 (vias/diaphragm opening)
- 17. Etch:** Plasma etch nitride and oxide for vias and diaphragm opening
- 18. Strip:** Strip photoresist
- 19. Clean:** RCA cleans, no HF dip
- 20. Metal:** Deposit 1  $\mu\text{m}$  of aluminum
- 21. Photolithography:** Mask 5 (aluminum)
- 22. Etch:** Remove Al with PAN etch
- 23. Strip:** Strip photoresist
- 24. Sinter:** Anneal contacts at 425°C, 30 minutes